

User Manual

MODEL: PCS-P100

Portable Pneumatic Pressure Calibrator



Table of Contents

1. General Introduction	2
1.1 Introduction	2
1.2 Features	2
1.3 Use	3
1.4 Calibrator Interface	4
1.5 Specifications	5
1.6 Ordering Information	6
1.7 Accessories	6
1.8 Optional items	7
2. Main Menu	8
2.1 Power on / off	8
2.2 Unit / Resolution / Zero Cal.	9~10
2.3 Slide	11
2.4 mA 2wire, 24V out / mA 3wire , 24V out	12
2.5 Vdc 3wire, 24V out / Screen switching	13
3. TASK Menu	14
3.1 TASK Menu	14
3.2 Max/Min/Avg	15
3.3 Leak Test	15
3.4 Switch Test	16
3.5 Setting	16
4. Operation	19
4.1 Basic Structure	19
4.2 Pressurize	20
4.3 Vacuum	23
5. Troubleshooting	26
5.1 Introduction	26
5.2 Symptom, Possible cause and Solution	26



1. General Introduction

1.1 Introduction

PCS-P100 is Portable pressure calibrator for Pneumatic pressure calibration up to 100 bar with pressure generation and precise control. An independent pressure calibration system combining electrical signal measuring and loop power to quickly and easily calibrate for a large amount of on-site calibration.

Using Dual-Stage lever type hand pump to generate up to 100 bar and quickly and easily, and then use the built-in volume controller to precisely adjust the pressure with the secondary fine pressure control.

PCS-P100 also has Pressure/vacuum switching valve to generate up to -0.97 bar in vacuum mode which has the best degree of a vacuum in its class.

Full-graphic touchscreen display with intuitive menu selection makes it high visibility and operability.

Upper side of PCS-P100 can equipped quick connectors and adaptors for quick and easy to connect UUT.

1.2 Features

- 1) Dual-Stage lever type hand pump to generate and control up to 100 bar
- 2) Dual-Stage lever type hand pump to generate and control up to -0.97 bar for vacuum
- 3) 0.02% F.S Accuracy
- 4) Electrical connection for Transmitter
 - Measure up to ±15 V, ±24 mA
 - Source up to 24 VDC
 - Loop Power
- 5) Pressure switch test, Help functions
- 6) Included carrying case
- 7) Available to apply pressure quick fittings (Optional)



1.3 Use

- 1) Portable pressure calibration
- 2) Simple calibration for common calibration lab
- 3) Calibrate pressure gauge for pressure measuring instruments retail business
- 4) Pressure generating and controlling for pressure test lab
- 5) Pressure calibration for laboratory
- 6) Pneumatic high pressure calibration
- 7) Easy & quick calibration for pressure transmitter, analog pressure gauge, digital pressure gauge, pressure switch test





1.4 Calibrator Interface



⑤ Pressure range

No.	Description	No.	Description
1	Test port	6	Pressure / Vacuum Switching valve
2	On / Off	7	Lever type hand pump
3	Full color touch screen display	8	Hand strap
4	Fine pressure adjustment	9	Electrical connections for measuring mA, V and detecting switch contacts.
5	Pressure range	10	Vent / release valve



1.5 General Specifications

Pressure range	-0.97 to 1100 bar, -0.7 bar to 0.7 bar
Accuracy	± 0.02% F.S
Electrical measurement	±15 V.dc, ±24 mA.dc,
and source	Accuracy ±(0.01% of Reading + 1digit), Loop Power
	Full color touch screen LCD, 110 mm(4.3") diagonal,
Display	480 x 272 pixels.,
	Resolution ±999999 (Available to select 4 to 6 digits.)
Power	Lithium-ion rechargeable battery, Charger 9V, 6A
TOWER	(5 hrs charge, 30 hrs battery life)
Workable	0 to 70 °c
Temperature Range	
Storage	-30 to 80 ℃
Temperature Range	
Temperature	0 to 50 ℃
Compensated Range	2
	Pa, hPa, kPa, MPa, bar, mbar, kg/cm ² , psi, mmH ₂ 0,
Pressure units	cmH ₂ 0, inH ₂ 0, mmHg, inHg, mSW, fSW
	(mSW and fSW units are applied on a water temperature of
	Table 2-10. Pressure Equivalent.)
Test Port	1/8" BSPP Female
Weight	4.2 kg including batteries
Size	210 mm(W) x 360 mm(D) x 110 mm(H)

Please charge the battery of PCS-P100 properly before storing it. Failure to do so may result in a complete battery drain.



1.6 Ordering Information

Model (PCS-P100_Range)	Description (Pressure Range)
0.7 bar	-0.7 bar to 0.7 bar
1 bar	-0.97 bar to 1 bar
2 bar	-0.97 bar to 2 bar
3.5 bar	-0.97 bar to 3.5 bar
7 bar	-0.97 bar to 7 bar
20 bar	-0.97 bar to 20 bar
35 bar	-0.97 bar to 35 bar
70 bar	-0.97 bar to 70 bar
100 bar	-0.97 bar to 100 bar

1.7 Accessories

1	2	3	(4)

Item	Quantity
① Carrying case	1
② Rechargeable battery	1
③ Battery charger	1
④ Test lead set	4



1.8 Optional Items

1	2	3	(4)	5
		0000	<image/>	

Item	Description
① Dirt / Moisture Trap	Up to 100 bar
② Pneumatic Quick-connection adaptor set	CA-P Series (1/4", 3/8", 1/2", 1/8" BSPT & BSPP, NPT)
③ Flexible tubes	FTH Series(30 cm to 300 cm)
④ Traceable calibration report with data	KOLAS CALIBRATION CERTIFICATE
5 External Pressure Manifold	Calibrate 2ea of UUT at once with hand-tight quick-connection

7



2. Main Menu

- 2.1 Power on / off
- 2.1.1 Power on



 Press and hold down Power button until ② screen shows. It will changes ② screen to ③ screen.

2.1.2 Power off



① Press and hold down Power button until in 0% to 100% on ② screen.



2.2 Unit / Resolution / Zero Cal.

2.2.1 Unit



The current pressure value is displayed, and the full scale and the green bar increases proportionally. This is a function that prevents internal sensor damage due to overpressure.

Touch units and scroll to change units Pa > hPa > kPa > MPa > bar > mbar > kg/cm² > psi > mmH₂0 > mH₂0 > inH₂0 > mmHg > inHg.

(If user has high pressure range, smallest units will not be indicated. For example, when user has 100 bar unit, mmH₂O will not indicates because after converted the unit, 7 digits cannot indicate on display.)

2.2.2 Resolution



User can select to digit number 4, 5 or 6. (Only in the units of pressure indicates in decimal point.)



2.2.3 Zero cal.



If pressure does not indicate zero when fully vented condition, touch $\[equation]$ to zeroing. Zeroing function only works when 0 ± 5% F.S. range.



2.3 Slide





2.4 mA 2wire , 24V out / mA 3wire , 24V out

2.4.1 mA 2wire , 24V out



Loop Power, Measure up to ±24mA, Supply up to 24 VDC.

2.4.2 mA 3wire , 24V out



Measure up to ±24mA, Supply up to 24 VDC.



2.5 Vdc 3wire , 24V out / Screen switching

2.5.1 Vdc 3wire , 24V out



Measure up to ±15V, Supply up to 24 VDC.

2.5.2 Screen switching





3. TASK Menu

3.1 TASK menu



Touch I to go to task set up menu. Max / Min test, Leak test, Switch test and Setting can be selectable.





3.2 Max / Min / Avg

PCS-P100	09:00 ኲ
Pressure Max 100.000	bar
1.	.000
UNIT	ZERO
Min&Ma	ax Test
Maximum	0.000
Mean	0.000
Minimum	0.000
✔ Reset	> Start
Â	

This function only can use in pressure measure mode. Indicates pressure maximum, minimum and average (Mean).

- 1) Touch **I** then select Max & Min
- 2) Touch **>** Start to start measure
- 3) Touch 🖌 Reset to reset the values

3.3 Leak Test



This function only can use in pressure measure mode. The leak test function is provided as a means of checking and quantifying the leaks that may be present in the system.

- 1) Touch **I** then select Leak Test
- 2) Touch **> Start** to start and stop the leak test.



3.4 Switch Test

PCS-P100	09:00 📖
Pressure Max 100,000	bar
1	.000
UNIT	ZERO
Switch	n Test
Opened at	0.000
Closed at	0.000
Hysteresis	0.000
✔ Reset	
Â	

This function only can use in pressure measure mode. Indicates opened and closed values when PCS sensed a change. The pressure difference between the change-of-states (i.e. OPEN-CLOSE or CLOSE-OPEN) value shows in Hysteresis.

Touch I then select Switch Test
 Touch Reset to reset the values

3.5 Setting

PCS-P100 09:00			
SETTING			
🛃 Time	∢	1) Time	: Set time
🛃 Cal. Pressure	<	2) Cal. Pressure	: Pressure Calibration
🗹 Cal. DMM	«	3) Cal. DMM	: DMM Calibration (Manufacture management mode)
🛃 About PCS	«·····	4) About PCS	: Current PCS information
🛃 System Config	g <u>«</u>	5) System Config	: System Configuration (Manufacture management mode)
^	.1		



3.5.1 Time



User can set time in Time page.

3.5.2 Cal.Pressure



User can calibrate the pressure values in Cal.Pressure page.



3.5.3 About PCS



User can see the current PCS information in About PCS page.



4. Operation

4.1 Basic Structure



 $\textcircled{6} \ \ \mathsf{Fine} \ \ \mathsf{pressure} \ \ \mathsf{adjustment} \\$

No.	Description
1	On / Off
2	Test port
3	Vent / release
4	Lever type hand pump
5	Charging port
6	Fine pressure adjustment
7	Pressure / Vacuum switching valve
8	Hand Strap Pin





4.2 Pressurize



⁽⁶⁾ Fine pressure adjustment



1) ② Connect the UUT to test port. (1/8" BSPP)







2) ⑦ Turn Pressure / Vacuum switching valve to CCW to Switching to ' P '.



3) ③ Turn Vent / Release valve to CW to close the Vent / Release valve.



4) ④ Generate the target pressure with Hand pump Pressing the pump up once without volume will apply approximately 1.6 to 2.0 bar of pressure. Short stroke will generate small pressure. Vacuum mode also.





5) ⑥ Using Fine adjust handle to control the target pressure.(CW to increase, CCW to decrease pressure)



6) After finished the test, Turn ③ Vent / Release valve to CCW to open the Vent/Release valve.

🚹 WARNING

- 1. PCS-P100 is pneumatic test and calibration purpose only.
- Do not switch between pressure and vacuum mode under pressure.
 Open the vent valve before switching between positive to vacuum pressures.
- 3. Low pressure gauges can very easily be over pressured if not careful. Please take caution when applying pressures.
- 4. Store the PCS-P100 in a dry non-corrosive environment.
- 5. PDK is not responsible for problems or damage resulting from improper use or operation of the equipment.



4.3 Vacuum





1) ② Connect the UUT to test port. (1/8" BSPP)





2) ⑦ Turn Pressure/Vacuum switching valve to CW to Switching to 'V'.



3) ③ Turn Vent/Release valve to CW to close the Vent/Release valve.



4) ④ Generate the target pressure with Hand pump Pressing the pump up once without volume will apply high vacuum. Short stroke will generate small vacuum.





5) ⑥ Using Fine adjust handle to control the target pressure. (CW to increase, CCW to decrease pressure)



6) After finished the test, Turn ③ Vent / Release valve to CCW to open the Vent/Release valve.

🚺 WARNING

- 1. PCS-P100 is pneumatic test and calibration purpose only.
- 2. Do not switch between pressure and vacuum mode under pressure. Open the vent valve before switching between positive to vacuum pressures.
- 3. Low pressure gauges can very easily be over pressured if not careful. Please take caution when applying pressures.
- 4. Store the PCS-P100 in a dry non-corrosive environment.
- 5. PDK is not responsible for problems or damage resulting from improper use or operation of the equipment.



5. Troubleshooting

5.1 Introduction

PCS-P100 is a sophisticated pressure setting and measuring instrument with advanced onboard features and functions. Before assuming that unexpected behavior is caused by a system defect or breakdown, the operator should use this manual and other training facilities to become thoroughly familiar with PCS-P100 operation. This troubleshooting guide is intended as an aid in identifying the reason for PCS-P100 behavior and determining whether the behavior is due to normal operation or an internal or external problem.

If the failure cannot be fixed, please stop system operation immediately and contact the manufacturer or authorized agent.

5.2 Symptom, Possible cause and Solution

Symptom	Possible cause	Solution
Product does not turn on	Not plugged in	Verify Product is plugged in and power and battery are available.
	No battery	Charge the battery.
	Others	contact the manufacturer or authorized agent.
Unable to use touch screen	Transient program error	Cycle power
	Display panel failure	contact the manufacturer or authorized agent.



Symptom	Possible cause	Solution
While using measure mode, pressure is leaking	Test port leak	Verify Test port is leak tight.
	UUT leak	Verify UUT is leak tight.
	Internal leak	contact the manufacturer or authorized agent.
Poor pressure control	Pressure supply too low	Verify pressure supply.
	External leak	Verify Test port and UUT are leak tight.
	Internal leak	contact the manufacturer or authorized agent.
Test port and Adaptor damage	Test port damaged	contact the manufacturer or authorized agent.
	Adaptor damage	Replace the adaptor
Others	-	contact the manufacturer or authorized agent.